		CLASSIFIED MESSAGE	A)TL SERBITINGSETSON AL ESSON ABOUT	OUTING
} \%\\$\\	and the state of t	SFCRE		3
, purpose to the secretary the sec	18387. 22 FEB 58			
70 1	DIRECTOR	EO 12958 3.3(b)(1)>25Y	SULAC	
FROM :				
action:	OSA (1-2-3-4-5-6-7-8-9-10) PRIORITY			
3MFO :	S/C (11)		A CHARLES OF THE PROPERTY OF T	
		AJY	PSS INCLUDED	
the construction of the state o	TOR: 1852Z 2: FEB 63	0-1		IN 66894
30	PRITY		CITE	8337
	OXCAPT			

ACFT 123 FLEW FLT NUMBER 44 ON 21 FEB FOR 2 HOURS AND 12 MIN TES. PILOT GILLILAND. PURPOSE TYPE II PACKAGE, PLUS V/H SINSOR TEST FOR BOTH TYPE I AND TYPE II. SCHEDULED RUNS OVER SAND LAKE TARGETS AT 30,000 FEET, 310 KEAS, ON SOUTHERLY First Run aborted due to no skab light, indicating HEIDING . PLATFORM NOT SKABILIZED. ROUGH AIR MAY HAVE BEEN FACTOR. MICOND RUN ABORTED FOR SAME REASON. THIRD, FOURTH, AND FIFTH SIXTH RUN ABORTED DUE NO STAB LIGHT. ROUGH AIR AGAIN RUNG OK. NOTED ON THIS RUN. SEVENTH RUN AGAIN NO STAB LIGHT, ALSO JUST BEFORE TARGETS ALL PACKAGE LIGHTS CAME ON INDICATING PACKAGE. MALFUNCTION. FULL SIGNIFICANCE OF THIS LAST EVENT STILL UN-DETERMINED. PACKAGE PEOPLE CONTINUING TO TROUBLE SHOOT TO ATTEMPT TO FIND. NORMAL LANDING WITH GOOD CHUTE, SORRY FOR DELAY THIS REPORT.

END OF MESSAGE

APPROVED FOR RELEASE DATE: AUG 2007

